


PARTS FOR:

STARTER / CHARGER 1000/120Amp 12/24V 415v/3ph MODEL: SUPERSTART1020.V3

ITEM

PART NO

1 OF 2



| 39 120.990439 Cable 40 120/322102 Plug, 41 120/322201 Whee |
|--|
|--|

| | 37 38 36 39 6 22 1 | |
|--------------|--------------------|-----------------|
| 15 | | _34 |
| <u>31</u> | | |
| <u>32</u> —— | | _(14) |
| 16 | | -(7) |
| 2 | | —(25) |
| 12 | | —(10) |
| 4 | | 3 |
| (17)——— | | <u>(8)</u> |
| 26 | | |

| 2 | 120/112131 | Rectifier (Pts/240) |
|----|------------|---------------------------|
| 3 | 120/112165 | Card |
| | 120/112182 | Protection, Rectifier |
| ; | 120/112296 | Knob, Timer |
| ; | 120/122400 | Switch, White Rocker |
| , | 120/122432 | Fuse (250V , 630Amp) |
| 3 | 120/122525 | Thermostat |
|) | 120/122649 | Switch (Sch 0814/7497) |
| 0 | 120/122694 | Contactor |
| 1 | 120/122725 | Switch, Green Rocker |
| 2 | 120.122796 | Thermostat |
| 3 | 120/123993 | Cable, Remote Control |
| 4 | 120/132244 | Mains Cable |
| 5 | 120/152134 | Ammeter |
| 6 | 120/164270 | Transformer, Auxiliary |
| 7 | 120/164748 | Transformer |
| 8 | 120.312399 | Handle |
| 9 | 120.322796 | Front Panel |
| 20 | 120.322798 | Foot |
| 21 | 120.322799 | Frame |
| 22 | 120.322901 | Switch Knob |
| 23 | 120.362034 | Clamp Holder |
| 24 | 120.483899 | Fuse Holder Box |
| 25 | 120.980528 | Diaphragm |
| 26 | 120.645343 | Bottom |
| 27 | 120.650557 | Fuse Cover |
| 28 | 120.681055 | Wheel Axle |
| 9 | 120.712025 | Positive Clamp |
| 80 | 120.712026 | Negative Clamp |
| 31 | 120/802131 | Fuse 100 Amp (pack of 10) |
| 32 | 120.980037 | Fuse Holder Clamp |
| 3 | 120.713121 | Cable 25Mmq 2.5M |
| 14 | 120.713120 | Cable 25Mmq 3M |
| 5 | 120.980487 | Back Panel |
| 6 | 120.980489 | Dashboard |
| 37 | 120/990162 | Terminal Complete |
| 88 | 120/990163 | Insulating Washers |
| 9 | 120.990439 | Cable Bushing Kit |
| 0 | 120/322102 | Plug, Wheel Retainer |
| 1 | 120/322201 | Wheel |
| | | |

DESCRIPTION

NOTE: It is our policy to continually improve products and as such we reserve the right to alter data, specifications and component parts without prior notice. **IMPORTANT:** No liability is accepted for incorrect use of product.

WARRANTY: Guarantee is 12 months from purchase date, proof of which will be required for any claim.

INFORMATION: For a copy of our latest catalogue and promotions call us on 01284 757525 and leave your full name and address, including postcode.














PARTS FOR:

STARTER / CHARGER 1000/120Amp 12/24V 415v/3ph MODEL: SUPERSTART1020.V3

2 OF 2

WIRING DIAGRAM



NOTE: It is our policy to continually improve products and as such we reserve the right to alter data, specifications and component parts without prior notice. IMPORTANT: No liability is accepted for incorrect use of product.

WARRANTY: Guarantee is 12 months from purchase date, proof of which will be required for any claim.

INFORMATION: For a copy of our latest catalogue and promotions call us on 01284 757525 and leave your full name and address, including postcode







